


1:Power line: Tricolor lines connected to U,V, W/
yellow-green line connected to ground
Temperature control line: two-phase of 110°C thermistor
connected to temperature protector
2:Cooling water outlet: (End 2 and 6 are connected with 8/6 hose)
3:Air return: 0.4-0.7MPa (6/4 hose)
4:Tool changing and dust-removing: 0.3-0.4MPa(6/4 hose)
5:Air seal: 0.1-0.2MPa(6/4 hose)
6:Encoder: reserved interface (no encoder for this model)
7:Cooling water inlet: delivery of water pump head 12m
(Don't connect wrong!)
8:Quantity of proximity switches: Two PNP(normally
open)N.O. for tool-mounting and tool-removing
Connection of proximity switch Brown line connected
to +24VDC ,and blue line connected to 0VDC
Connect the positive pole of signal load to black wire/negative pole
to 0VDC
9:Air inlet while tool removing: 0.4-0.7MPa(6/4 hose)
10:Hanging ring: applied for mounting

Note: PNP (normally open) N.O. connecting method of proximity
switch
Brown line connected to +24VDC, and blue line connected to
0VDC
Connect the positive pole of signal load to +24VDC/negative
pole to black wire

Parameters of PTC three-core thermistor	
DC Power Supply	MaximumDC25V/100mA
-20~25°C	≤300Ω
≤90°C	≤750Ω
105°C	≤1650Ω
110°C	Rated function temperature
115°C	≥3990Ω
≥125°C	≥12KΩ
≤160°C	Maximum storage temperature



Model: GDL125Y-30-18Z/16
Type: Permanent magnet synchronization

Rated Voltage: 380V

Rated Power: 16kw

Rated Current: 30A

Rated Frequency: 600Hz

Rated Speed: 18000rpm

Maximum Frequency: 800Hz

Maximum Speed: 24000rpm

Number of Pole: 4P

Phase: 3

Rotation Direction: Counterclockwise viewed from the
end of spindle extension

Tool Holder: BT30 (Parfaite recommended)

Pop-rivet: BT30-45° (Parfaite recommended)

Weight: 30KG

Special warning:

- 1.The spindle shall be mounted to the clamping position;otherwise
it would damage the bearing!
- 2.It shall not change tools before complete stop of spindle.The manual tool-
changing button shall be unavailable while spindle is rotating;otherwise it
would cause the block of spindle!
- 3.The spindle can only be started after air return for air cylinder (piston reset),
otherwise, it may cause the spindle stucked!
- 4.It shall ensure the dedusting air circuit is open to prevent dust or foreign
materials from entering the spindle while changing tools!
- 5.The air seal shall be kept normally open!
- 6.The compressed air shall be clean and dry with filtering precision of 0.1 μm.
Air sealing shall be normally open.It is recommended to apply two levels of
filtering with precisions of 0.5μm/0.1μm, and the filter shall be equipped with
automatic drainage.
- 7.During the operation, the frequency converter shall be set strictly according to
the U-f curve of the spindle