

Model GDL125-30-24Z/7.5C

Voltage 380V

Power 7.5kw

Current 15.0A

Frequency 800Hz

Rotation 24000rpm

Number of poles 4P


Phase 3

Rotation Direction Counterclockwise viewed
from the end of spindle
extension

Tool Holder BT30(Parfaite recommended)

Pop-rivet BT30-45°(Parfaite recommended)

Weight 32KG



- 1:Power line: Tricolor lines connected to U,V, W/
yellow-green line connected to ground
Temperature control line: two-phase of 110℃ thermistor
connected to temperature protector
- 2:Cooling water outlet: (End 2 and 7 are connected with 8/6 hose)
- 3:Air return: 0.4-0.7MPa (6/4 hose)
- 4:Tool changing and dust-removing: 0.3-0.4MPa(6/4 hose)
- 5:Air seal: 0.1-0.2MPa(6/4 hose)
- 6:Encoder: GS04T08MIS,A/B/Z 1024pprTTL
square wave signal output
- 7:Cooling water inlet: delivery of water pump head 12m
(Don't connect wrong!)
- 8:Quantity of proximity switches: Two PNP(normally
open)N.O. for tool-mounting and tool-removing
Connection of proximity switch Brown line connected
to +24VDC ,and blue line connected to 0VDC
Connect the positive pole of signal load to black wire/negative pole
to 0VDC
- 9:Air inlet while tool removing: 0.4-0.7MPa(6/4 hose)
- 10:Hanging ring: applied for mounting

Parameters of PTC three-core thermistor	
DC power supply	Maximum DC25V/100mA
-20~25℃	≤300Ω
≤90℃	≤750Ω
105℃	≤1650Ω
110℃	Rated function temperature
115℃	≥3990Ω
≥125℃	≥12KΩ
≤160℃	Maximum storage temperature

Encoder wiring instructions	
Signal	Colour
VCC+5V	Brown
GND	White
A+	Green
A-	Yellow
B+	Blue
B-	Red
Z+	Grey
Z-	Pink
External isolation(shielding)	
The encoder wire is about 1m long,supplied in loose wire,and wired according to wire color.	

Special warning:

- 1.The spindle shall be mounted to the clamping position;otherwise
it would damage the bearing!
- 2.It shall not change tools before complete stop of spindle.The manual tool-
changing button shall be unavailable while spindle is rotating;otherwise it
would cause the block of spindle!
- 3.The spindle can only be started after air return for air cylinder (piston reset),
otherwise, it may cause the spindle stucked!
- 4.It shall ensure the dedusting air circuit is open to prevent dust or foreign
materials from entering the spindle while changing tools!
- 5.The air seal shall be kept normally open!
- 6.The compressed air shall be clean and dry with filtering precision of 0.1 μm!
Air sealing shall be normally open.It is recommended to apply two levels of
filtering with precisions of 0.5μm/0.1μm, and the filter shall be equipped with
automatic drainage.
- 7.During the operation, the frequency converter shall be set strictly according to
the U-f curve of the spindle

						Universal cylinder with encoder			Jiangsu HQD Spindle Motor Co., Ltd.	
Marks	Number of places	Zoning	Modified document number	Signature	Date					
Designed by			Standardized by			Phase mark	Weight	Scale	Profile Drawing	
Reviewed by										
Processed by			Approved by			Total page(s)	Page		GDL125-30-24Z/7.5C-00-1	