
## GDF46-18Z/2.2 380V Outline diagram



Special attention: thread locking adhesive shall be applied or the spring washer shall be added to prevent the looseness during the installation of the fastening screw!