







Interface Description

Pin arrangement of electrical connector (aviation plug).

Pins	Description
1	U motor phase
2	V motor phase
3	W motor phase
4	
5	Connect yellow-green earth wire
6	Temperature sensor TC-130
7	Temperature sensor TC-130



2. Cooling air inlet: Inlet pressure 0.4 MPa(ø8 quick-plug)

3. Seal gas: Pressure 0.2~0.3MPa(ø8 quick-plug)

Note: The use of this spindle necessitates the activation of the seal gas!