


Left view




Clockwise rotation viewed from the spindle nose to the small spindle at the rear end ER16 nut is of left-hand thread

Wiring description

Pins	four-core socket
1	U-converter phase
2	V-converter phase
3	W-converter phase
4	Grounding wire

Counterclockwise rotation viewed from the spindle nose to the big spindle at the front end



Power: 3.0Kw

Voltage: 220V/380V

Current: 10A/5.5A

Rotational speed: 24000r/min

Frequency: 400Hz

Bearing: 2X7005C/2X7004C

Nut: ER20 and ER16 Left

Weight: 10KG