



Wiring description

| Pins | four-core socket |
|------|--------------------------|
| 1 | U-converter phase |
| 2 | V-converter phase |
| 3 | W-converter phase |
| 4 | Grounding wire \ominus |