




### Wiring description

| Pins | four-core socket                                                                                   |
|------|----------------------------------------------------------------------------------------------------|
| 1    | U-converter phase                                                                                  |
| 2    | V-converter phase                                                                                  |
| 3    | W-converter phase                                                                                  |
| 4    | Grounding wire  |